

101025, 822

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,752,373 B1
DATED : June 22, 2004
INVENTOR(S) : N.A. Rudy et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 1,

Line 66, "WO 93/10950" should read -- WO 93/10950 --

Column 4,

Line 51, "assemblies and 21," should read -- assemblies 20 and 21, --

Column 5,

Line 46, "1in" should read -- 130 in --

Column 6,

Line 43, "mounting plate have recesses" should read -- mounting plate 110 have recesses --

Line 60, "arm 116 20 and" should read -- arm 116 and --

Column 7,

Line 19, "1and" should read -- 120 and --

Line 39, "1may" should read -- 120 may --

Line 48, "1of" should read -- 125 of --

Column 10,


Line 55, "rotatable" should read -- rotatably --

Column 14,

Line 3, "rotatable" should read -- rotatably --

Signed and Sealed this

Twenty-first Day of December, 2004



JON W. DUDAS
Director of the United States Patent and Trademark Office